Processing KODAK PROFESSIONAL Black-and-White Films

Kodak alaris

TECHNICAL DATA / BLACK-AND-WHITE FILM

April 2018 • ED-BWF

The following are starting-point recommendations for processing KODAK PROFESSIONAL Black-and-White Films with KODAK Chemicals. For best results, make tests to determine the best development time for your application.

Note: Development times shorter than 5 minutes may produce unsatisfactory uniformity.

KODAK PROFESSIONAL Film	Film Code					
			20°C (68°F)	24°C (75°F)		
		KODAK PROFESSIONAL XTOL Developer	KODAK PROFESSIONAL D-76 Developer	KODAK PROFESSIONAL HC-110 Developer (Dilution B)	KODAK PROFESSIONAL T-MAX Developer (1:4)	Reference Publication
T-MAX 100						
T-MAX 100 FILM 100 TMX TOOTAL RECEIPTION	100TMX	71/2	61/2	6	61/4	F-4016
T-MAX 400						
T-MAX 400 FILM 400 TMY 400 TMY	400TMY	6 ¹ /2	7 1/2	5 ¹ /2	5 ¹ /2	F-4043
TRI-X 400						
TRI-X 400 FILM <u> <u> </u> <u> </u></u>	400TX	7	6 ³ /4	3 ³ /4	4 ³ /4	F-4017

Roll Films: Small Tank Film Processing (Intermittent Agitation for Tanks That Can Be Inverted)

Processing KODAK PROFESSIONAL Black-and-White Films

KODAK PROFESSIONAL Film	Film Code	Development Time (Minutes)					
			20°C (68°F)	24°C (75°F)			
		KODAK PROFESSIONAL XTOL Developer	KODAK PROFESSIONAL D-76 Developer	KODAK PROFESSIONAL HC-110 Developer (Dilution B)	KODAK PROFESSIONAL T-MAX RS Developer and Replenisher (1:4)	Reference Publication	
T-MAX 100	100TMX	6 ³ /4	5 ³ /4	51/2	5 ³ /4	F-4016	
T-MAX 400	400TMY	6	6 ³ /4	5 ¹ /4	4	F-4043	
TRI-X 320	320TXP	6	6	3 1/4	NR	F-4017	

Sheet Films: Tray Processing

Final Steps in Processing Black-and-White Film

Step/Solution	Time (min:sec)	Temperature	Comments
Rinse/stop bath	0:30	18 to 24°C (65 to 75°F)	Agitate continuously. Rinse with a stop bath such as: • KODAK PROFESSIONAL Indicator Stop Bath (1:63)
Fix	2:00 to 4:00* with a liquid-concentrate (L) fixer -OR- 5:00 to 10:00* with a powder (P) fixer		Agitate continuously for the first 30 seconds and at 30-second intervals after that with a hardening fixer such as: • KODAK PROFESSIONAL Rapid Fixer (liquid) • KODAFIX Solution (liquid) • KODAK PROFESSIONAL POLYMAX Fixer (liquid) • KODAK PROFESSIONAL Fixer (powder) Fix for twice as long as it takes the film to clear (lose its milky appearance). See instructions for the specific fixer. IMPORTANT: With KODAK PROFESSIONAL T-MAX Films, fixer will be exhausted more rapidly than with other films. If negatives show a magenta (pink) stain after fixing, fixer may be near exhaustion, or fixing time is too short. If the stain is pronounced and irregular, refix the film in fresh fixer.
Rinse	0:30		Rinse the film in the tank under running water.
Wash aid	1:00 to 2:00		Treat with KODAK PROFESSIONAL Hypo Clearing Agent. Agitate continuously for the first 30 seconds and then at 30-second intervals.
Wash	5:00		Run the wash water at least fast enough to provide a complete change of water in the container in 5 minutes. For rapid washing in a small tank, fill the tank to overflowing with fresh water and then dump it all out. Repeat this cycle 10 times.
Final rinse/wetting agent	0:30		To minimize drying marks, treat the film with KODAK PROFESSIONAL PHOTO-FLO Solution after washing. Provide gentle agitation for 5 seconds of the total time.
Dry	_		Hang the film to dry film in a dust-free place. You may wipe the surfaces carefully with a soft viscose sponge to remove excess liquid. Store dry negatives in sleeves or envelopes away from dust and extreme temperature and humidity.

* Times are approximate. Refer to the film or developer instructions.

© 2018 Kodak Alaris Inc. TM/MC/MR: D-76, Dektol, HC-110, Photo-Flo, Polymax, T-Max, and Xtol The Kodak, Kodak Professional, Estar, Kodafix, T-Grain, Tri-X, and Wratten trademarks are used under license from Eastman Kodak Company.

Processing KODAK PROFESSIONAL Black-and-White Films KODAK Publication No. ED-BWF Revised 4-18

KODAK ALARIS • ROCHESTER, NY 14615

Kodak alaris